



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
 EPA Method: 600/R-93/116 and  
 40 CFR, Part 763, Subpart E, App.E



**Customer:** JTL Services  
 3999 Sanderosa Rd.  
 Fayetteville, NC 28312

**Attn:** Jay Leonard

**Lab Order ID:** 10075471

**Analysis:** PLM

**Date Received:** 02/21/2025

**Date Reported:** 02/21/2025

**Project:** COF - ECDD 1210 Durden Lane,  
 Fayetteville, NC 28303

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
1	Ceiling Surfacing	2% Chrysotile		98% Other	White Non-Fibrous Homogeneous
10075471_0001					Crushed
2 - A	Ceiling mix	2% Chrysotile	1% Other	97% Other	White Non-Fibrous Homogeneous
10075471_0002	texture				Crushed
2 - B	Ceiling mix	None Detected		100% Other	White Non-Fibrous Homogeneous
10075471_0009	finish				Crushed
2 - C	Ceiling mix	None Detected		100% Other	Tan Non-Fibrous Homogeneous
10075471_0010	base				Crushed
2 - D	Ceiling mix	None Detected	10% Cellulose	90% Gypsum	White Fibrous Homogeneous
10075471_0011	sheetrock				Crushed
3	Joint compound	2% Chrysotile	1% Other	97% Other	White Non-Fibrous Homogeneous
10075471_0003					Crushed
4	Flooring	20% Chrysotile	5% Cellulose	75% Other	Brown Fibrous Homogeneous
10075471_0004	inseparable mastic				Dissolved, Teased
5	glue	None Detected		100% Other	Brown Non-Fibrous Homogeneous
10075471_0005					Dissolved, Crushed

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Charmel Dozier (11)

**Analyst**

**Approved Signatory**



# Bulk Asbestos Analysis

By Polarized Light Microscopy  
EPA Method: 600/R-93/116 and  
40 CFR, Part 763, Subpart E, App.E



**Customer:** JTL Services  
3999 Sanderosa Rd.  
Fayetteville, NC 28312

**Attn:** Jay Leonard

**Lab Order ID:** 10075471

**Analysis:** PLM

**Date Received:** 02/21/2025

**Date Reported:** 02/21/2025

**Project:** COF - ECDD 1210 Durden Lane,  
Fayetteville, NC 28303

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
6	grout	None Detected		100% Other	White Non-Fibrous Homogeneous Crushed
10075471_0006					
7	Ceiling Surfacing	2% Chrysotile	1% Other	97% Other	White Non-Fibrous Homogeneous Crushed
10075471_0007					
8	Shingle	None Detected	30% Cellulose	70% Other	Black Fibrous Homogeneous Dissolved
10075471_0008					

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogenous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Insitute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Charmel Dozier (11)

Analyst

Approved Signatory