

**REPORT OF THE ASBESTOS SURVEY**

*COF - ECDD - 822 Varsity Drive,  
Fayetteville, NC 28301  
0428-97-5847*

**PURPOSE AND SCOPE**

An asbestos survey was conducted on February 17, 2025. The purpose of the asbestos inspection of this structure was to locate the asbestos containing building materials (ACBM) to protect human health and the environment. Information in this report should be made available to persons that may come in contact with the asbestos containing materials (ACM) as a result of demolition, repairs, or a change in ownership.

**PROJECT DESCRIPTION**

A limited survey was performed on the interior and exterior space. No below grade inspection performed. Not responsible for any ACBM found during demolition.

**PROCEDURE**

No building plans were available. I was given unlimited access to the Structure. During the walk-through, areas of suspect materials were identified. Representative samples of these materials were collected and analyzed via Polarized Light Microscopy by an NVLAP accredited laboratory.

**RESULTS**

As you review the data, you will find the following materials were determined to have ASBESTOS:

**ACBM – No suspect materials found in this structure.**

If this material is not rendered friable (reduced to powder by hand pressure, also interpreted as chipping, sanding, or grinding), the material does not have to be removed. If, however, this material is made friable, i.e. during demolition, replacement, or renovations, a North Carolina accredited asbestos abatement contractor should perform the removal. Any questions concerning the removal should be directed to the number listed below.

The NESHAP regulation dated Tuesday, November 20, 1990, Part III Environmental Protection Agency, 40CFR Part 61, requires that any building being renovated or demolished be inspected for asbestos containing building materials.

**NOTE:** If this structure is going to be demolished, or moved an asbestos permit application and notification for demolition/renovation is required by law to be mailed to the address below 10 working days prior to demolition or asbestos abatement activities.

Health Hazards Control Branch  
Occupational and Environmental Epidemiology

Section  
NC Department of Environment  
Raleigh, NC, 27626-0820  
Telephone: (919) 733-0820

An asbestos inspection is a judgement call based on the experience of the inspector. The survey is conducted by sampling substances known to contain asbestos or by sampling materials suspected of containing asbestos.

I the inspector assume no liability for asbestos materials that are not included in an asbestos inspection due to the material being inaccessible, concealed, or not considered suspect ACM. I the inspector assume no liability for the condition of the building materials before or after the inspection.

Sincerely,

JTL 2-18-2025

John T. Leonard  
Asbestos Inspector  
NC Accreditation # 12254











